


PE100



## SDR 11



|          | DN<br>[mm] | d1<br>[mm] | D<br>[mm] | le1<br>[mm] | L<br>[mm] | K<br>[mm] | n | ød<br>[mm] | M  | hC<br>[mm] | kg    |
|----------|------------|------------|-----------|-------------|-----------|-----------|---|------------|----|------------|-------|
| 43009252 | 200        | 250        | 340       | 180         | 240       | 295       | 8 | 22         | 20 | 60         | 11,00 |