


PE100



## SDR 11



|          | DN<br>[mm] | d1<br>[mm] | D<br>[mm] | le1<br>[mm] | L<br>[mm] | K<br>[mm] | n | ød<br>[mm] | M  | hC<br>[mm] | kg   |
|----------|------------|------------|-----------|-------------|-----------|-----------|---|------------|----|------------|------|
| 43010112 | 80         | 110        | 200       | 60          | 100       | 160       | 8 | 18         | 16 | 40         | 2,40 |