


PE100



## SDR 11



|          | DN<br>[mm] | d1<br>[mm] | D<br>[mm] | le1<br>[mm] | L<br>[mm] | K<br>[mm] | n  | ød<br>[mm] | M  | hc<br>[mm] | kg    |
|----------|------------|------------|-----------|-------------|-----------|-----------|----|------------|----|------------|-------|
| 43011404 | 400        | 400        | 580       | 300         | 475       | 525       | 16 | 30         | 27 | 105        | 60,20 |