


PE100



SDR 11



	d1 [mm]	le1 [mm]	L [mm]	z1 [mm]	z2 [mm]	kg
42003402	400	300	1000	500	500	50,10