


PE100



## SDR 11



|          | d1<br>[mm] | d2<br>[mm] | le1<br>[mm] | le2<br>[mm] | L<br>[mm] | z1<br>[mm] | z2<br>[mm] | kg    |
|----------|------------|------------|-------------|-------------|-----------|------------|------------|-------|
| 42940112 | 400        | 110        | 300         | 150         | 825       | 412,5      | 381        | 36,31 |