


PE100



## SDR 11



|          | DN<br>[mm] | d1<br>[mm] | D<br>[mm] | le1<br>[mm] | L<br>[mm] | K<br>[mm] | n  | ød<br>[mm] | M  | hc<br>[mm] | kg     |
|----------|------------|------------|-----------|-------------|-----------|-----------|----|------------|----|------------|--------|
| 43011634 | 600        | 630        | 840       | 350         | 545       | 770       | 20 | 36         | 33 | 125        | 142,30 |