


PE100



SDR 11



|          | DN<br>[mm] | d1<br>[mm] | D<br>[mm] | L<br>[mm] | K<br>[mm] | n  | ød<br>[mm] | M  | hC<br>[mm] | kg    |
|----------|------------|------------|-----------|-----------|-----------|----|------------|----|------------|-------|
| 43012562 | 600        | 560        | 780       | 190       | 725       | 20 | 30         | 27 | 120        | 94,70 |